

NDT Technician – Field Operation

Conduct a non-destructive examination, using real time radiography techniques with an industrial x-ray inspection system on the customer site, of customer product in order to identify defects.

Job Description:

- Operate x-ray equipment and robotic equipment at the Customer location in accordance with applicable operating procedures.
- Load items to be inspected from pallet onto a conveyor system using a power hoist.
- Disposition parts as good or reject/failed.
- Ensure good parts proceed down conveyance system to the partner company operation.
- Unload rejected parts and place them on pallet
- Maintain and clean the x-ray equipment and robots, as required, to ensure continued satisfactory operation.
- Input data to customer computer system.
- Complete the operating and safety records, as required.
- Interface and liaise with customer and partner personnel regarding all aspects of the day-to-day production operation.
- Repair equipment, as needed and where practicable given skill level and experience.
- Provide specialized assistance to internal sales personnel and customers by acting upon a variety of requests.
- Help to train, develop and mentor new Technicians

Essential Skills:

- HS Diploma or equivalent.
- At least 2 years of experience in a hands-on technical role in an industrial environment.
- Established verbal and written communication skills.
- Ability to handle the physical requirements of the position, to include:
 - operation of a power hoist
 - lifting up to fifty (50) pound alone or heavier items with assistance
 - Sitting and standing in alternating one (1) hour shifts over the course of the work shift
 - Lifting, bending, walking and maneuvering as required to load and unload parts
- Capable of working within the rugged dusty industrial environment
- Positive attitude and ability to work under pressure in a fast paced team environment.
- Ability to accept change and adapt to new policies and procedures.
- Legally authorized to work in the US and able to successfully pass a complete background check and drug test.

Non-essential Skills:

- Associates Degree or Degree or Certification from an Accredited Technical Trade School
- Certification as a Limited level II NDT Technician in Radiographic Testing – Digital Radiography by ASNT or under VJT's SNT-TC-1A compliant written practice
- Experience operating a forklift, power hoist, pallet jack, or other manual and powered material movement and lifting equipment.